

SAFETY ALERT



The below information has been issued on behalf of the EFFC to make others aware of the potential risks and possible precautions to take in order to avoid these.

Date/Time of Incident: 23/09/2020

Type of Incident: To be retracted into the rotary linkage.

Nature of Incident/Injury: Skin abrasions.

Details of Incident: A subcontractor drilled inclined boreholes into the shoring for the horizontal exploration of explosive ordnance. The safety vest of an employee was pulled into the system's rotating linkage and the employee was detected. The employee suffered skin abrasions.



Action Taken, Lessons Learnt: Use device with safety equipment for emergency shutdown only e.g. Switch rope, proximity protection etc. Do not stay in danger area. Wear tightly fitting workwear. Instruction.